


2/5



SUBSTITUTE SHEET (RULE 26)


3/5

						10	6	8	7		11	9	6	က
	11	10	6	8		6	5	4	3		7:	9	5	က
	7	9	5	4		2	-	0	C		3	2	-	က
	3	2	-	0		×	×	×	×		၁	×	×	က
'										1 ,				
						6	8	2	9		11	10	6	7
	11	10	9	8		5	4	3	2		2	9	5	2
	7	9	5	4		1	0	ပ	В		ε	2	-	2
	က	2	-	0		×	×	×	×		၁	В	×	2
က										ı ,				
FIG.						8	2	9	2		11	10	6	-
	11	10	6	8		4	3	2	1		7	9	5	-
	7	9	2	4		0	C	В	А		က	2	1	-
	3	2	-	0		×	×	×	×		ပ	В	4	-
						.						,		
											=	9	6	0
	=	10	6	8		7	9	2	4		7	9	2	0
	7	9	5	4		3	2	-	0		က	2	-	0
	3	2	1	0		×	×	×	×		×	×	×	0
		2	_		-		Ė					((HES	

ALIGNMENT 2 BITS UNUSED BYTE A 8 BITS FIG. 4 BYTE B 8 BITS BYTE C 8 BITS

FIG. 5

ALIGNMENT	ALIGNMENT DATA POSITION	RESIDUE BYTES USED
00	DATA STARTS ON ADDRESS WITH A1=0, A0=0 (ZERO OFF) NONE	NONE
10	DATA STARTS ON ADDRESS WITH A1=0, A0=1 (ONE OFF)	BYTE A & B & C
10	DATA STARTS ON ADDRESS WITH A1=1, A0=0 (TWO OFF) BYTE B & C	BYTE B & C
=	DATA STARTS ON ADDRESS WITH A1=1, A0=1 (THREE OFF) BYTE C	BYTEC



SUBSTITUTE SHEET (RULE 26)